


geoprobe.com/oip

Direct Image® Logging Tools



\*Switching from UV to G is a swap of the probe and power supply.

**Running OIP without HPT**

To run OIP without HPT, you need to plug off the HPT port on the probe (HPT Port Plug 226700) and use the tools above.

**Note**

CPT options are available in the OIHPT/MIHPT - CPT Sub section

Soil Imaging Probe patent pending

### Instruments, Controllers

Components	Part	MN	Notes
	Field Instrument	213940	110V
		213941	220V
	OIP Instrument Interface	224720	100-220VAC
	HPT Flow Controller	214091	110V
		214093	220V

### Probes

Components	Part	MN	Notes
	OIHPT-UV Probe	227466	UV275
	OIHPT-G Probe	231346	GL525

### Trunklines & Accessories

Components	Part	MN	Notes
	OIHPT Trunkline	228253	100 ft.
		228254	150 ft.
		231482	200 ft.
	OIHPT-UV Power Supply	228265	
	OIHPT-G Power Supply	231345	
	Trunkline Seal Spacers (Pair)	207596	Pair - Use with V1 Drive Heads
	MIHPT/OIHPT/HTL Trunkline Seal, Red V1	211768	Use with V1 Drive Heads
	MIHPT Trunkline Seal, Black V2	248787	Use with V2 Drive Heads

### 1.75 in. Components

Components	Part	MN	Notes
	1.75 RHSL Box x 1.75 RHML Pin V1 Drive Head	220130	4.08 in. S-S
	1.75 RHSL Box x 1.75 RHML Pin V2 Drive Head	247976	4.08 in. S-S
	O-Ring (1.75 in. Probe Rod)	220387	Quantity: 25
	1.75 RHSL Box x 1.5 RHML Pin V1 Drive Head	220545	4.50 in. S-S
	1.75 RHSL Box x 1.5 RHML Pin V2 Drive Head	250333	4.50 in. S-S
	O-Ring (1.5 in. Probe Rod)	202695	Quantity: 25
	1.75 Connection Tube With Friction Reducer	225827	2.13 in. OD
	1.75 in. Connection Tube	219594	

S-S (Shoulder to Shoulder)

### Accessories

Components	Part	MN	Notes
	OIP Window Assembly	231838	4 mm
	O-Ring (1.75 in. threaded DI Probes)	223575	Quantity: 10
	OIP Window Seals	224959	Quantity: 10
	OIP Window Ratchet Wrench Assembly	225140	
	OIP Window Ratchet Wrench Head Assembly	225139	
	Four Sided Cuvette Holder Assembly	225952	
	Cuvette Quartz 3500 uL	112784	Quantity: 2
	EC Dipole Tester	205724	
	OIP Service Kit	226361	
	HPT Service Kit	205599	
	OIP Test Load	228240	
	OIP Trunkline Pigtail	227458	Down Hole End
	OIP Trunkline Pigtail	227459	Down Hole End
	OIP Trunkline Pigtail	227461	Up Hole End
	OIP Trunkline Pigtail	227462	Up Hole End
	Brass Barb MIHPT/OIHPT TL to HPT Sensor	220978	Quantity: 5
	Band Clamp No. 7	220976	Quantity: 10
	Band Clamp No. 5	220977	Quantity: 10
	HPT Reference Cylinder	212689	For 1.75 in. and smaller probes
	HPT Reference Cylinder	211762	For 2.25 in. probes
	HPT Reference Block	249505	
	1.75 in. Solid Drive Point	222652	2.0 in. OD
	1.5 in. Solid Drive Point	202637	1.7 in. OD, 1.5 in. Rod Thread

## OIHPT Step by Step

[geoprobe.com/](http://geoprobe.com/)



This step by step demo goes through setup and sampling with the OIHPT system.